

To: scott.hansen@millelacsband.com[scott.hansen@millelacsband.com]
From: Restaino, Mark
Sent: Mon 4/29/2013 2:04:47 PM
Subject: RE: Emailing: DOC137

Scott,

I contacted the manager and asked for the past line test and automatic line leak detector test. I know they will probably hire Oday to conduct those test this week, but maybe we will get lucky and they will have past tests.

We had a brief discussion in the office. We plan to meet with the attorney's next week and to discuss the next steps. At this point I think that we have everything we need to know, let's wait until after this meeting to discuss this site. That way I can give you more information. Of course if there was additional information you think we should know I would be glad to talk to you prior to meeting with the attorneys.

Thanks.

-Mark

-----Original Message-----

From: Scott Hansen [mailto:Scott.Hansen@millelacsband.com]
Sent: Thursday, April 25, 2013 4:28 PM
To: Restaino, Mark
Subject: RE: Emailing: DOC137

Mark,
I'm going to be out of the office Friday, lets talk Monday.
I can make it work anytime Monday.
Scott

Scott Hansen
Environmental Program Manager
Mille Lacs Band DNR/E
(320) 532-7445 business
(320) 532-7514 fax
(320) 630 2439 cell

-----Original Message-----

From: Restaino, Mark [mailto:restaino.mark@epa.gov]
Sent: Thursday, April 25, 2013 3:59 PM
To: Scott Hansen
Cc: Galbraith, Erin
Subject: RE: Emailing: DOC137

Scott,

Are you available tomorrow?

We may need to get the attorney and Sherry involved with Mellen's.

-Mark

-----Original Message-----

From: Scott Hansen [mailto:Scott.Hansen@millelacsband.com]

Sent: Thursday, April 25, 2013 3:47 PM

To: Restaino, Mark

Cc: Galbraith, Erin

Subject: FW: Emailing: DOC137

Mark,

I stopped by Meleens for an inspection, no records could be located by the new manager Melissa Huff, to the best of her knowledge they were being sent to Erin. I inspected all the fills, sumps and three out of four of the dispensers. On dispenser 1, (attached photo) there was product leaking (premium) I had new manager come out and I showed her and said that it needed to be corrected ASAP.

I left a copy of the CP test and informed them to schedule a retest as required ASAP. I tested the top 9 inches of top soil and it appeared thawed.

They have an OPW 1500, and I can set up a three ring folder to help them Track tank tests by month. New manager was not familiar with system.

I stopped by Frederickson Marina and called his cell phone at 11:15 left a message about the need to inspect system by April 29, 2013.

I have not heard back.

Let's discuss.

Scott

Scott Hansen
Environmental Program Manager
Mille Lacs Band DNR/E
(320) 532-7445 business
(320) 532-7514 fax
(320) 630 2439 cell

-----Original Message-----

From: Ryan Rupp

Sent: Thursday, April 25, 2013 3:13 PM

To: Scott Hansen

Subject: Emailing: DOC137

Your message is ready to be sent with the following file or link attachments:

DOC137

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.